









$d_0$	$\varnothing 10\text{mm}$







**A8**

	$h_{nom} = 85\text{mm}$	$t_{fix2} = 0 \dots 10\text{mm}$
HUS3-HF 10	$t_{fix1}$	$t_{fix1} + t_{fix2}$
10x100	15 mm	15...25 mm
10x110	25 mm	25...35 mm






$d_0$	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$



**B5**

	$h_{nom1}$	$h_{nom2}$	$h_{nom3}$
HUS3-HF 10	=55mm	=75mm	=85mm
	$t_{fix1}$	$t_{fix2}$	$t_{fix3}$
10x60	5 mm	-	-
10x80	25 mm	5 mm	-
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm



	$d_0$
$\varnothing 10\text{mm}$	

